



Columbia Center: Sewer Drain and Potable Pipe System Rehabilitation

Location: Downtown San Diego, California

Situation:

Corroded sewer stacks and potable water stacks were showing their age. The sewer stacks include 228 feet of cast iron drain pipes from the 7th floor to the 25th floor. The potable stacks reach 120 feet to supply drinking fountains and kitchens.

Solution:

Cleaned and rehabilitated 19 stories of piping to prevent future corrosion and back-ups. Nu Flow's trenchless structural liner and patented epoxy coating solutions did not disrupt workers or destroy the office building's walls, ceilings, finishes and custom wallpaper.

