



Maryland House of Delegates Building: Roof Drains and HVAC Rehabilitation

Location: Annapolis, Maryland

Situation:

The Maryland House of Delegates' Lowe Office Building had leaking roof drains, which range from 3" to 5" in diameter, and a failing HVAC pipe system, about 1.5 miles of black iron pipes that range from 2.5" to 4" in diameter. The customer did not want the building's structure disturbed during the work.

Solution:

While the Lowe Office Building underwent a \$9 million renovation, Nu Flow successfully cleaned and lined the aged roof drains and HVAC pipe system without causing destruction to the building or disturbing the other contractors. Nu Flow's trenchless solutions greatly extended the useful life of the pipe systems.

